



FIGURE E1A
 PHOTOGRAPHS OF FLOODING ON THE 15 FEBRAURAY 2010
 WAGONGA INLET CATCHMENT



Above: Flooding at the corner of Lynch Street and Brice Street at approximately 3pm



Above: Lynch Street, near the junction with Nichelsen Street (Narooma Newspaper)



Above: McMillian Street



Above: Flooding of the Bowling Green and Bill Smyth Memorial Oval behind it at approximately 3pm



Above: 8 Lynch Street, near the junction with Nichelsen Street



Above: Riverside Dr (Narooma Newspaper)



Above: Flooding on Bluewater Drive near the intersection with Bay Street

FIGURE E1B
PHOTOGRAPHS OF FLOODING ON THE 15 FEBRAURAY 2010
DUCK POND AND KIANGA LAKE CATCHMENTS



Above: DUCK POND – Junction of Eucalyptus Drive and Dalmeny Drive
 at approximately 3pm



Above: DUCK POND – Dalmeny Dr
 (Narooma Newspaper)



Above: DUCK POND – Eucalyptus Dr
 (Narooma Newspaper)



Above: KIANGA LAKE – Junction of Princes Hwy and Kianga Rd
 (Narooma Newspaper)



Above: KIANGA LAKE – Kianga Ck downstream of Princes Hwy
 (Narooma Newspaper)



Above: KIANGA LAKE – Junction of Dalmeny Dr and Centenary Dr
 (Narooma Newspaper)



Above: KIANGA LAKE –Dalmeny Dr Bridge
 (Narooma Newspaper)

FIGURE E1C
PHOTOGRAPHS OF FLOODING ON THE 15 FEBRAURAY 2010
MUMMUGA LAKE CATCHMENT



Above: Dalmeny Pedestrian Bridge, over Mummuga Lake
on the 16th February 2010



Above: Corner of Binalong Street,
at approximately 10:30am



Above: Acacia Close



Above: Mummuga Lake ICOLL entrance was open to the ocean at the time of photo
at approximately 10:30am



Above: Corner of Binalong Street
time unknown



Above: Mort Ave, opposite the Dalmeny Fire Brigade Hall,
at approximately 3pm



Above: Mort Ave, Dalmeny Fire Brigade Hall
(Narooma Newspaper)

FIGURE E1D
PHOTOGRAPHS OF FLOODING ON THE 14 OCTOBER 2014
WAGONGA INLET CATCHMENT



Above: Flooding at Brice Street



Above: Flooding of the Bowling Green



Above: Flooding on Bill Smyth Oval



Above: Lynch Street, near the junction with Nichelsen Street



Above: Riverside Drive



Above: McMillian Street



Above: Panorama at McMillian Road

FIGURE E1E
PHOTOGRAPHS OF FLOODING ON THE 14 OCTOBER 2014
MUMMUGA LAKE CATCHMENT



Above: Flood water in the front yard of properties on Mort Avenue



Above: Flood water inside garage on Mort Avenue



Above: Channel between Mort Avenue and Tatiara Street (upstream of Mort Avenue)



Above: Channel between Mort Avenue and Tatiara Street (upstream of Mort Avenue)



Above: White-wash from flow discharging into Mummuga Lake from the channel between Mort Avenue and Tatiara Street (downstream of Mort Avenue)



Above: White-wash from flow discharging into Mummuga Lake from the channel between Mort Avenue and Tatiara Street (downstream of Mort Avenue)